


Heritage Record Report

of

ELSA

As-found Location:
700 kilometres (435 miles) to the North of Whitehorse
at Mile 60.3 of the Silver Trail, Yukon Highway 11
Yukon, Canada

for
Government of Yukon
Tourism and Culture
Corporate Services
Box 2703
Whitehorse, Yukon, Y1A 2C6

Project Contact
Barbara Hogan
Historic Sites Registrar
Historic Sites, Cultural Services Branch
Government of Yukon L-2
Box 2703
Whitehorse, Yukon Y1A 2C6
Telephone 867.667.8258 Fax 867.667.8023
E-mail Barbara.Hogan@gov.yk.ca

by

K.D. Drafting Ltd.
Heritage Recording

Project Coordinator
Kevin Dombrosky
Heritage Recorder, C.E.T.
10815 - 128 Street
Edmonton, Alberta Canada T5M 0W3
Telephone & Fax 780.454.5155
Cell 780.238.5155
E-mail kddrafting@telus.net

September 2009

Volume 2

Building #17
New Bunkhouse

YUKON ENERGY, MINES
& RESOURCES LIBRARY
P.O. Box 2703 (K-335)
Whitehorse, Yukon Y1A 2C6

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-001.JPG	**Photo 17-001**	Extant Record Photographic Key Sheet Page Number:



YUKON ENERGY, MINES
& RESOURCES LIBRARY
P.O. Box 2703 (K-335)
Whitehorse, Yukon Y1A 2C6

Photo Description **Exterior view** from the Southwest.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-002.JPG	**Photo 17-002**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Exterior view.** South elevation.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-003.JPG	**Photo 17-003**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Exterior view** from the Southeast.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-004.JPG	**Photo 17-004**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view** from the Southeast.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-005.JPG	**Photo 17-005**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Exterior view** from the Southeast.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-006.JPG	**Photo 17-006**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Exterior view.** Left end of East elevation.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-007.JPG	**Photo 17-007**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Exterior view.** Center of East elevation.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-008.JPG	**Photo 17-008**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** Right end of East elevation.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-009.JPG	**Photo 17-009**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** at Northeast corner.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-010.JPG	**Photo 17-010**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view** at Northeast corner looking along the North elevation.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-011.JPG	**Photo 17-011**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view** at Northwest corner looking along the North elevation.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-012.JPG	**Photo 17-012**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** at Northwest corner looking along the West elevation.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-013.JPG	**Photo 17-013**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** at Southwest corner looking along the West elevation.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-101.JPG	**Photo 17-101**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view.** Entry Corridor 101. View towards the North.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-102.JPG	**Photo 17-102**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Entry Corridor 101. View towards the South.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-103.JPG	**Photo 17-103**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Room 102. East elevation. South wall partly missing.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-104.JPG	**Photo 17-104**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Room 102. North elevation. South wall partly missing.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-105.JPG	**Photo 17-105**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Room 103. North elevation.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-106.JPG	**Photo 17-106**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Room 103. South elevation.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-107.JPG	**Photo 17-107**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Room 103. View towards the Northeast.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-108.JPG	**Photo 17-108**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Room 104. South elevation.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-109.JPG	**Photo 17-109**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Room 104. North elevation.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-110.JPG	**Photo 17-110**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Room 105. West elevation.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-111.JPG	**Photo 17-111**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Room 105. East elevation.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-112.JPG	**Photo 17-112**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Room 106. South elevation.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-113.JPG	**Photo 17-113**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Room 106. North elevation.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-114.JPG	**Photo 17-114**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Room 107. View towards the Southwest.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-115.JPG	**Photo 17-115**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Room 107. View towards the Northeast.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-116.JPG	**Photo 17-116**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Room 108.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-117.JPG	**Photo 17-117**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Room 108.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-118.JPG	**Photo 17-118**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Room 109. View towards the South.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-119.JPG	**Photo 17-119**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Room 109. View towards the West.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-120.JPG	**Photo 17-120**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Locker Room 110. View towards the South.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-121.JPG	**Photo 17-121**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Locker Room 110. View towards the North on the West side of the lockers.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-122.JPG	**Photo 17-122**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Locker Room 110. View towards the North on the East side of the lockers.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-123.JPG	**Photo 17-123**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Locker Room 110. View towards the West on the North side of the lockers.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-124.JPG	**Photo 17-124**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Washroom 111. View towards the East.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-125.JPG	**Photo 17-125**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Washroom 111. View towards the West.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-126.JPG	**Photo 17-126**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Rear Entry 112. View towards the Southwest corner.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-127.JPG	**Photo 17-127**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Rear Entry 112. View towards the Northeast corner.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-128.JPG	**Photo 17-128**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Mechanical Room 113. View towards the West.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-129.JPG	**Photo 17-129**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Mechanical Room 113. View towards the East.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-130.JPG	**Photo 17-130**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Dry Room 114. View towards the East along North wall.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-131.JPG	**Photo 17-131**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Dry Room 114. View towards the Northeast corner.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-132.JPG	**Photo 17-132**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Interior view.** Dry Room 114. View towards the East.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-133.JPG	**Photo 17-133**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Dry Room 114. View towards the East.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-134.JPG	**Photo 17-134**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Dry Room 114. View towards the North along the West wall.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-135.JPG	**Photo 17-135**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Change Room 115. View towards the West.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-136.JPG	**Photo 17-136**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Change Room 115. View towards the Southeast corner.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-137.JPG	**Photo 17-137**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Change Room 115. North elevation.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-138.JPG	**Photo 17-138**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Washroom 116. View towards the West.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-139.JPG	**Photo 17-139**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Shower Room 116. View towards the Northeast.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-140.JPG	**Photo 17-140**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view.** Locker Room 117. View towards the South.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-141.JPG	**Photo 17-141**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Locker Room 117. View towards the East.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-142.JPG	**Photo 17-142**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Gang Shower Room 118. View towards the West.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-143.JPG	**Photo 17-143**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Gang Shower Room 118. View towards the East.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-144.JPG	**Photo 17-144**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Gang Shower Room 118. View towards the East.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-145.JPG	**Photo 17-145**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Gang Shower Room 118. View towards the West.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-146.JPG	**Photo 17-146**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view.** Sink Room 119. View towards the South.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-147.JPG	**Photo 17-147**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Sink Room 119. View towards the East.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-148.JPG	**Photo 17-148**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Sink Room 119. View towards the Northwest at the access from the Corridor 121.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-149.JPG	**Photo 17-149**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Toilet Area 120. View towards the West.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-150.JPG	**Photo 17-150**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Toilet Area 120. View towards the East.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-151.JPG	**Photo 17-151**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Corridor 121. View towards the North.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-152.JPG	**Photo 17-152**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view.** Corridor 121. View towards the South.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-153.JPG	**Photo 17-153**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Laundry 122. View towards the Southwest corner.

Building #17 - Dry / Change Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 17-154.JPG	**Photo 17-154**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Laundry 122. View towards the Northeast corner.

Building #19 - Fire Assay Office

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 19-001.JPG	**Photo 19-001**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Southwest.

Building #19 - Fire Assay Office

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 19-002.JPG	**Photo 19-002**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** South elevation.

Building #19 - Fire Assay Office

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 19-003.JPG	**Photo 19-003**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Southeast.

Building #19 - Fire Assay Office

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 19-004.JPG	**Photo 19-004**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** East elevation.

Building #19 - Fire Assay Office

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 19-005.JPG	**Photo 19-005**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Exterior view** from the Northeast.

Building #19 - Fire Assay Office

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 19-006.JPG	**Photo 19-006**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Exterior view.** North elevation.

Building #19 - Fire Assay Office

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 19-007.JPG	**Photo 19-007**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Northwest.

Building #19 - Fire Assay Office

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 19-008.JPG	**Photo 19-008**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view** from the Southwest corner along the West side of the building.

Building #19 - Fire Assay Office

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 19-101.JPG	**Photo 19-101**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Furnace Room 101. East elevation. Right side. Door to concrete vault.

Building #19 - Fire Assay Office

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 19-102.JPG	**Photo 19-102**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Furnace Room 101. East elevation. Left side.

Building #19 - Fire Assay Office

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 19-103.JPG	**Photo 19-103**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Furnace Room 101. North elevation.

Building #19 - Fire Assay Office

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 19-104.JPG	**Photo 19-104**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Furnace Room 101. North elevation. Left side.

Building #19 - Fire Assay Office

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 19-105.JPG	**Photo 19-105**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view.** Furnace Room 101. North elevation.

Building #19 - Fire Assay Office

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 19-106.JPG	**Photo 19-106**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view.** Furnace Room 101. South elevation. Concrete vault on left side.

Building #37 - Assay Lab

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 37-001.JPG	**Photo 37-001**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Southeast.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-002.JPG	**Photo 37-002**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** East elevation.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-003.JPG	**Photo 37-003**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Exterior view** from the Northeast.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-004.JPG	**Photo 37-004**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Northeast. Building entrance on the left.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-005.JPG	**Photo 37-005**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Exterior view** from the Northeast corner. Looking West.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-006.JPG	**Photo 37-006**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Exterior view** from the Northwest. Looking Eastward.

Building #37 - Assay Lab

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 37-007.JPG	**Photo 37-007**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Northwest.

Building #37 - Assay Lab

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 37-008.JPG	**Photo 37-008**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** West elevation.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-009.JPG	**Photo 37-009**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** West elevation. Left side.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-010.JPG	**Photo 37-010**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** West elevation. Right side.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-011.JPG	**Photo 37-011**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** View from Northwest corner at Basement level looking Southward.

Building #37 - Assay Lab

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 37-012.JPG	**Photo 37-012**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Southwest.

Building #37 - Assay Lab

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 37-013.JPG	**Photo 37-013**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Southwest towards the East.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-014.JPG	**Photo 37014-**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Southeast.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-101.JPG	**Photo 37-101**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. East Basement.** Room B01. East elevation.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-102.JPG	**Photo 37-102**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. East Basement.** Room B01. West elevation.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-103.JPG	**Photo 37-103**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. East Basement.** Room B01. North elevation.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-104.JPG	**Photo 37-104**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view. East Basement.** Washroom B02. North elevation.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-105.JPG	**Photo 37-105**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. East Basement.** Washroom B02. West elevation. Metal lockers and pressure tank.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-106.JPG	**Photo 37-106**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view. East Basement.** Room B03. East elevation. Concrete table.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-107.JPG	**Photo 37-107**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. East Basement.** Room B03. View of Southwest corner. Concrete table.

Building #37 - Assay Lab

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 37-108.JPG	**Photo 37-108**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. East Basement.** Room B04. View of Northwest corner.

Building #37 - Assay Lab

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 37-109.JPG	**Photo 37-109**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. East Basement.** Room B04. View of Southeast corner.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-110.JPG	**Photo 37-110**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. East Basement.** Room B04. View of Northeast corner.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-111.JPG	**Photo 37-111**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view. East Basement.** Room B04. View of Southwest corner.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-112.JPG	**Photo 37-112**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. East Basement.** Room B01. Left side of North elevation. Stairwell to 1st floor.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-113.JPG	**Photo 37-113**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. West Basement.** Room B05. East elevation.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-114.JPG	**Photo 37-114**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. West Basement.** Room B05. East elevation.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-115.JPG	**Photo 37-115**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. West Basement.** Room B05. West elevation.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-116.JPG	**Photo 37-116**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view. West Basement.** Room B05. West elevation. Concrete table legs from 1st floor table.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-117.JPG	**Photo 37-117**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Entry vestibule to Corridor 101.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-118.JPG	**Photo 37-118**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Corridor 101. West elevation.

Building #37 - Assay Lab

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 37-119.JPG	**Photo 37-119**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Corridor 101. East elevation.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-120.JPG	**Photo 37-120**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Lab 102. View towards the Northwest corner.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-121.JPG	**Photo 37-121**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view. 1st Floor.** Lab 102. View towards the Northeast corner.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-122.JPG	**Photo 37-122**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Lab 102. View towards the Southeast corner.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-123.JPG	**Photo 37-123**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Lab 102. View towards the Southwest corner.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-124.JPG	**Photo 37-124**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Lab 103. View towards the Southeast corner.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-125.JPG	**Photo 37-125**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Lab 103. View towards the Northeast corner.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-126.JPG	**Photo 37-126**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Lab 103. View towards the Northwest corner.

Building #37 - Assay Lab

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 37-127.JPG	**Photo 37-127**	Extant Record Photographic Key Sheet Page Number: A9.1



Photo Description **Interior view. 1st Floor.** Lab 103. View towards the Southwest corner.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-128.JPG	**Photo 37-128**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view. 1st Floor.** Stairwell 104. North elevation.

Building #37 - Assay Lab

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 37-129.JPG	**Photo 37-129**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view. 1st Floor.** Stairwell 104. South elevation from intermediate stair landing.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-130.JPG	**Photo 37-130**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Office 105. South elevation.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-131.JPG	**Photo 37-131**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Office 105. North elevation.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-132.JPG	**Photo 37-132**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Room 106. East elevation.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-133.JPG	**Photo 37-**	Extant Record Photographic Key Sheet Page Number: A9.1



Photo Description **Interior view. 1st Floor.** Room 106. West elevation.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-134.JPG	**Photo 37-134**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Interior view. 1st Floor.** Room 107. View of Southwest corner.

Building #37 - Assay Lab

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 37-135.JPG	**Photo 37-135**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Room 107. View of Northeast corner.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-136.JPG	**Photo 37-136**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Room 108. North elevation.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-137.JPG	**Photo 37-137**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view. 1st Floor.** Room 108. View of Southeast corner.

Building #37 - Assay Lab

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 37-138.JPG	**Photo 37-138**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Room 108. South elevation.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-139.JPG	**Photo 37-139**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Room 108. View of Northwest corner.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-140.JPG	**Photo 37-140**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Room 108. East elevation. Stair assembly to Attic Space.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-141.JPG	**Photo 37-141**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view. 1st Floor.** Room 109. West elevation.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-142.JPG	**Photo 37-142**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view. 1st Floor.** Room 109. North elevation.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-143.JPG	**Photo 37-143**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Room 109. View to Southwest corner.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-144.JPG	**Photo 37-144**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Room 109. View to West along South wall.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-145.JPG	**Photo 37-145**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Corridor 101. View towards the East.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-146.JPG	**Photo 37-146**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Corridor 101. View towards the West.

Building #37 - Assay Lab

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 37-147.JPG	**Photo 37-147**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Room 110. View to the Southeast corner.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-148.JPG	**Photo 37-148**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Room 110. Right side of East elevation.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-149.JPG	**Photo 37-149**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Room 110. View to the Northeast corner.

Building #37 - Assay Lab

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 37-150.JPG	**Photo 37-150**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Room 110. View to the Northwest corner.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-151.JPG	**Photo 37-151**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Room 111. View to the Northeast corner.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-152.JPG	**Photo 37-152**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Room 111. View to the Southwest corner.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-153.JPG	**Photo 37-153**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. Attic Space.** Left side of East elevation.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-154.JPG	**Photo 37-154**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. Attic Space.** Right side of West elevation.

Building #37 - Assay Lab

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 37-155.JPG	**Photo 37-155**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. Attic Space.** View looking West down access stairwell.

Building #37 - Assay Lab

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 37-156.JPG	**Photo 37-156**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view. Attic Space.** Left side of West elevation.

Building #37 - Assay Lab

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 37-157.JPG	**Photo 37-157**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. Attic Space.** Right side of East elevation.

Building #36
New Bunkhouse

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-001.JPG	**Photo 38-001**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** East elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-002.JPG	**Photo 38-002**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Northeast.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-003.JPG	**Photo 38-003**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Exterior view.** Left side of North elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-004.JPG	**Photo 38-004**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** Right side of North elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-005.JPG	**Photo 38-005**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** Left side of North elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-006.JPG	**Photo 38-006**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** Center of North elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-007.JPG	**Photo 38-007**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view.** Right side of North elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-008.JPG	**Photo 38-008**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view** from the Northwest corner.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-009.JPG	**Photo 38-009**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view.** West elevation. View towards the South.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-010.JPG	**Photo 38-010**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view.** West elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-011.JPG	**Photo 38-011**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** Right side of West elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-012.JPG	**Photo 38-012**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Exterior view.** South elevation. View towards the East.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-013.JPG	**Photo 38-013**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Exterior view.** South elevation. View towards the West.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-014.JPG	**Photo 38-014**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** View of Southeast corner.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-015.JPG	**Photo 38-015**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** Left side of East elevation. Exterior wall removed to expose concrete vault.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-101.JPG	**Photo 38-101**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Entry Vestibule 101. North elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-102.JPG	**Photo 38-102**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view. 1st Floor.** Common Area 102. Left side of South elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-103.JPG	**Photo 38-103**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view. 1st Floor.** Common Area 102. West elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-104.JPG	**Photo 38-104**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Common Area 102. Right side of South elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-105.JPG	**Photo 38-105**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Office 103. View of Northeast corner.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-106.JPG	**Photo 38-106**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Office 103. South elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-107.JPG	**Photo 38-107**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view. 1st Floor.** Office 104. View of Northwest corner.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-108.JPG	**Photo 38-108**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Office 104. View of Southeast corner.

YUKON ENERGY, MINES & RESOURCES LIBRARY
P.O. Box 2703 (K-335)
Whitehorse, Yukon Y1A

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-109.JPG	**Photo 38-109**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Office 105. View of Southwest corner.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-110.JPG	**Photo 38-110**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view. 1st Floor.** Office 105. View of Northeast corner.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-111.JPG	**Photo 38-111**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Electrical Room 106. East elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-112.JPG	**Photo 38-112**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Interior view. 1st Floor.** Electrical Room 106. West elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-113.JPG	**Photo 38-113**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Room 107. East elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-114.JPG	**Photo 38-114**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Interior view. 1st Floor.** Room 107. West elevation.

Building #38 - Administration Building

As-found Location: Elsa, Yukon

Photo ID Number: 38-115.JPG	**Photo 38-115**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Concrete Vault 108. West elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-116.JPG	**Photo 38-116**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Interior view. 1st Floor.** Concrete Vault 108. East elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-117.JPG	**Photo 38-117**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Office 109. North elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-118.JPG	**Photo 38-118**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Office 109. South elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-119.JPG	**Photo 38-119**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view. 1st Floor.** Office 110. View of Northwest corner.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-120.JPG	**Photo 38-120**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Office 110. View of Southeast corner.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-121.JPG	**Photo 38-121**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view. 2nd Floor.** Office 201. View of Northwest corner.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-122.JPG	**Photo 38-122**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view. 2nd Floor.** Office 201. View of Southeast corner.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-123.JPG	**Photo 38-123**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view. 2nd Floor.** Office 202. View of Northwest corner.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-124.JPG	**Photo 38-124**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Interior view. 2nd Floor.** Office 202. View of Southeast corner.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-125.JPG	**Photo 38-125**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view. 2nd Floor.** Office 203. View of Northwest corner.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-126.JPG	**Photo 38-126**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view. 2nd Floor.** Office 203. View of Southeast corner.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-127.JPG	**Photo 38-127**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Interior view. 2nd Floor.** Office Boardroom 204. View of Northeast corner.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-128.JPG	**Photo 38-128**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view. 2nd Floor.** Office Boardroom 204. View of Southeast corner.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-129.JPG	**Photo 38-129**	Extant Record Photographic Key Sheet Page Number:



Photo Description Description

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-130.JPG	**Photo 38-130**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Office 205. View of Northwest corner.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-131.JPG	**Photo 38-131**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Washroom 206. South elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-132.JPG	**Photo 38-132**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Interior view. 2nd Floor.** Washroom 206. View of Northwest corner.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-133.JPG	**Photo 38-133**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Office 207. North elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-134.JPG	**Photo 38-134**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view. 2nd Floor.** Office 207. View of Southeast corner.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-135.JPG	**Photo 38-135**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Washroom 208. View of Northeast corner.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-136.JPG	**Photo 38-136**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Washroom 208. East wall.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-137.JPG	**Photo 38-137-**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Office 209. West elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-138.JPG	**Photo 38-138**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Office 209. View of Northeast corner.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-139.JPG	**Photo 38-139**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Common Area 210. Stairwell at West elevation.

Building #38 - Administration Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 38-140.JPG	**Photo 38-140**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Common Area 210. East elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-001.JPG	**Photo 39-001**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view** from the Southeast.

Building #39 - Staff House

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 39-002.JPG	**Photo 39-002**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** Right side of East elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-003.JPG	**Photo 39-003**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** Left side of East elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-004.JPG	**Photo 39-004**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** East elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-005.JPG	**Photo 39-005**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from Northeast corner.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-006.JPG	**Photo 39-006**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from Northeast corner.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-007.JPG	**Photo 39-007**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from Northwest corner along North elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-008.JPG	**Photo 39-008**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from Northwest corner along West elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-009.JPG	**Photo 39-009**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from Northeast corner. West elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-010.JPG	**Photo 39-010**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view.** Left side of West elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-011.JPG	**Photo 39-011**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from Southwest corner.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-101.JPG	**Photo 39-101**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view. 1st Floor.** Entry Vestibule 101. North elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-102.JPG	**Photo 39-102**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Room 102. View of Northeast corner.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-103.JPG	**Photo 39-103**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Room 102. West elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-104.JPG	**Photo 39-104**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Kitchen 103. West elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-105.JPG	**Photo 39-105**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view. 1st Floor.** Kitchen 103. East elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-106.JPG	**Photo 39-106**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Corridor 104. South elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-107.JPG	**Photo 39-107**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Corridor 104. North elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-108.JPG	**Photo 39-108**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view. 1st Floor.** Washroom 105. South elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-109.JPG	**Photo 39-109**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Corridor 106. West elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-110.JPG	**Photo 39-110**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Interior view. 1st Floor.** Washroom 107. South elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-111.JPG	**Photo 39-111**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view. 1st Floor.** Washroom 107. South elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-112.JPG	**Photo 39-112**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view. 1st Floor.** Washroom 107. North elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-113.JPG	**Photo 39-113**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Interior view. 1st Floor.** Bathroom 108. South elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-114.JPG	**Photo 39-114**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view. 1st Floor.** Laundry 109. South elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-115.JPG	**Photo 39-115**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Laundry 109. North elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-116.JPG	**Photo 39-116**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Bedroom 110. View of Southeast corner.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-117.JPG	**Photo 39-117**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Interior view. 1st Floor.** Bedroom 110. North elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-118.JPG	**Photo 39-118**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Bedroom 110. West elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-119.JPG	**Photo 39-119**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view. 1st Floor.** Storage Room 111. South elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-120.JPG	**Photo 39-120**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Bedroom 112. North elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-121.JPG	**Photo 39-121**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view. 1st Floor.** Bedroom 112. South elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-122.JPG	**Photo 39-122**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Storage Room 113. North elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-123.JPG	**Photo 39-123**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Storage Room 113. South elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-124.JPG	**Photo 39-124**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Corridor 201. West elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-125.JPG	**Photo 39-125**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view. 2nd Floor.** Corridor 201. East elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-126.JPG	**Photo 39-126**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Corridor 201. West elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-127.JPG	**Photo 39-127**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Bedroom 202. South elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-128.JPG	**Photo 39-128**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Bedroom 203. View towards the Southeast corner.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-129.JPG	**Photo 39-129**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Interior view. 2nd Floor.** Bedroom 204. View towards the Northeast corner.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-130.JPG	**Photo 39-130**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Interior view. 2nd Floor.** Bedroom 205. North elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-131.JPG	**Photo 39-131**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Washroom 212. View towards the Northwest corner.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-132.JPG	**Photo 39-132**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Interior view. 2nd Floor.** Bathroom 213. South elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-133.JPG	**Photo 39-133**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view. 2nd Floor.** Washroom 214. South elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-134.JPG	**Photo 39-134**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Washroom 214. North elevation.

Building #39 - Staff House

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 39-135.JPG	**Photo 39-135**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Interior view. 2nd Floor.** Stairwell 215. South elevation.

Building #40 - Garage

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 40-001.JPG	**Photo 40-001**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view.** North elevation.

Building #40 - Garage

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 40-002.JPG	**Photo 40-002**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Northeast.

Building #40 - Garage

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 40-003.JPG	**Photo 40-003**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Northeast. East elevation.

Building #40 - Garage

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 40-004.JPG	**Photo 40-004**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Southeast.

Building #40 - Garage

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 40-005.JPG	**Photo 40-005**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Southeast along the South wall.

Building #40 - Garage

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 40-006.JPG	**Photo 40-006**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Exterior view.** South elevation.

Building #40 - Garage

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 40-007.JPG	**Photo 40-007**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Southwest.

Building #40 - Garage

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 40-008.JPG	**Photo 40-008**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view** from the Northwest. West elevation.

Building #40 - Garage

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 40-009.JPG	**Photo 40-009**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Northwest.

Building #40 - Garage

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 40-101.JPG	**Photo 40-101**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Room 101. South elevation.

Building #40 - Garage

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 40-102.JPG	**Photo 40-102**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Room 101. North elevation.

Building #40 - Garage

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 40-103.JPG	**Photo 40-103**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Room 101. South elevation. Workbench and shelving.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-001.JPG	**Photo 41-001**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Southwest.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-002.JPG	**Photo 41-002**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Exterior view.** Left side of South elevation.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-003.JPG	**Photo 41-003**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Exterior view.** Right side of South elevation.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-004.JPG	**Photo 41-004**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Exterior view** from the Southeast.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-005.JPG	**Photo 41-005**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Northeast.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-006.JPG	**Photo 41-006**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Northeast above the sheds against East wall.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-007.JPG	**Photo 41-007**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Exterior view** from the Northeast. Sheds against East wall.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-008.JPG	**Photo 41-008**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Northeast along the North wall.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-009.JPG	**Photo 41-009**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Exterior view** from the Northeast towards the shed against the East wall.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-010.JPG	**Photo 41-010**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** Left side of North wall.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-011.JPG	**Photo 41-011**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** of the North elevation from the Northwest corner.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-012.JPG	**Photo 41-012**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** View from the left side of North wall towards the West.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-013.JPG	**Photo 41-013**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** of the Northwest corner.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-014.JPG	**Photo 41-014**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** West elevation. 2nd Floor.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-015.JPG	**Photo 41-015**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** West elevation. Center of 1st Floor.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-016.JPG	**Photo 41-016**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Exterior view.** Right side of West elevation.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-017.JPG	**Photo 41-017**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** Left side of West elevation.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-018.JPG	**Photo 41-018**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Northwest corner.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-019.JPG	**Photo 41-019**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view** from the Southwest corner.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-101.JPG	**Photo 41-101**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Entry Vestibule 101. South elevation.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-102.JPG	**Photo 41-102**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Entry Vestibule 101. North elevation.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-103.JPG	**Photo 41-103**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Lobby 102. South elevation.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-104.JPG	**Photo 41-104**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Lobby 102. North elevation.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-105.JPG	**Photo 41-105**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Lobby 102. South elevation. Stair assembly to 2nd floor.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-106.JPG	**Photo 41-106**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Kitchen 103. View of the Northeast corner.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-107.JPG	**Photo 41-107**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Interior view. 1st Floor.** Entry 104. West elevation. Dining area on right.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-108.JPG	**Photo 41-108**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view. 1st Floor.** Entry 104. View towards the Southeast corner.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-109.JPG	**Photo 41-109**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view. 1st Floor.** Entry 104. West elevation.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-110.JPG	**Photo 41-110**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Bedroom 105. View towards the Southeast.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-111.JPG	**Photo 41-111**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Dining area 108. View towards the Northwest.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-112.JPG	**Photo 41-112**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Bathroom 109. South elevation.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-113.JPG	**Photo 41-113**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view. 1st Floor.** Bedroom 105. North elevation.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-114.JPG	**Photo 41-114**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Bathroom 106. South elevation.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-115.JPG	**Photo 41-115**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Bathroom 106. North elevation.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-116.JPG	**Photo 41-116**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Entry 107. West elevation.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-117.JPG	**Photo 41-117**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Kitchen 108. View towards the Northeast.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-118.JPG	**Photo 41-118**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Bathroom 109. View towards the Northwest.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-119.JPG	**Photo 41-119**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Bedroom 110. View towards the Southeast corner.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-120.JPG	**Photo 41-120**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 1st Floor.** Bedroom 110. View towards the Northwest corner.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-121.JPG	**Photo 41-121**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Entry 201. West elevation.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-122.JPG	**Photo 41-122**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Kitchen 202. View towards the Northwest corner.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-123.JPG	**Photo 41-123**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Kitchen 202. View towards the Northeast corner.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-124.JPG	**Photo 41-124**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Bedroom 203. View towards the Northwest corner.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-125.JPG	**Photo 41-125**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view. 2nd Floor.** Bedroom 203. View towards the Southeast corner.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-126.JPG	**Photo 41-126**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Bedroom 211. View towards the Southeast corner.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-127.JPG	**Photo 41-127**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Bathroom 204. South elevation.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-128.JPG	**Photo 41-128**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Bathroom 204. View towards the Northeast.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-129.JPG	**Photo 41-129**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Interior view. 2nd Floor.** Laundry Room 205. North elevation.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-130.JPG	**Photo 41-130**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Interior view. 2nd Floor.** Stairwell 206. South elevation.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-131.JPG	**Photo 41-131**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Entry 207. West elevation.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-132.JPG	**Photo 41-132**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Living Room 208. View towards the Northwest corner.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-133.JPG	**Photo 41-133**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Kitchen 209. East elevation.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-134.JPG	**Photo 41-134**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Bathroom 210. South elevation.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-135.JPG	**Photo 41-135**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Bathroom 210. View towards the Southwest.

Building #41 - Apartment Building

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 41-136.JPG	**Photo 41-136**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view. 2nd Floor.** Bedroom 211. View towards the Northwest corner.

Building #42
New Bunkhouse

Building #42 - Garage

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 42-001.JPG	**Photo 42-001**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Northeast.

Building #42 - Garage

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 42-002.JPG	**Photo 42-002**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** East elevation.

Building #42 - Garage

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 42-003.JPG	**Photo 42-003**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** North elevation.

Building #42 - Garage

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 42-004.JPG	**Photo 42-004**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Northwest.

Building #42 - Garage

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 42-005.JPG	**Photo 42-005**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Northwest.

Building #42 - Garage

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 42-006.JPG	**Photo 42-006**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Southwest corner along the West wall.

Building #42 - Garage

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 42-007.JPG	**Photo 42-007**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Southeast.

Building #42 - Garage

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 42-008.JPG	**Photo 42-008**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view** from the Southeast.

Building #42 - Garage

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 42-101.JPG	**Photo 42-101**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Room 101. East elevation.

Building #42 - Garage

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 42-102.JPG	**Photo 42-102**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view.** Room 101. West elevation.

Building #42 - Garage

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 42-103.JPG	**Photo 42-103**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Room 102. West elevation.

Building #42 - Garage

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 42-104.JPG	**Photo 42-104**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view.** Room 102. East elevation.

Building #43
New Bunkhouse

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-001.JPG	**Photo 43-001**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Exterior view.** South elevation.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-002.JPG	**Photo 43-002**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view.** Left side of South elevation.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-003.JPG	**Photo 43-003**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view.** Right side of South elevation.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-004.JPG	**Photo 43-004**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view** of Southeast corner.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-005.JPG	**Photo 43-005**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** of Southeast corner.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-006.JPG	**Photo 43-006**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** Right side of East elevation.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-007.JPG	**Photo 43-007**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** Left side of East elevation.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-008.JPG	**Photo 43-008**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** of Northeast corner.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-009.JPG	**Photo 43-009**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** of Northeast corner.

Building #43 - Church

As-found Location: Elsa, Yukon

Photo ID Number: 43-010.JPG	**Photo 43-010**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view.** North elevation.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-011.JPG	**Photo 43-011**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view** of Northwest corner.

Building #43 - Church

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 43-012.JPG	**Photo 43-012**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view** of Northwest corner.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-013.JPG	**Photo 43-013**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** of West wall looking South.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-014.JPG	**Photo 43-014**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** of West wall looking South.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-015.JPG	**Photo 43-015**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** of Northwest corner.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-016.JPG	**Photo 43-016**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view.** West elevation.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-017.JPG	**Photo 43-017**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** of West side of tower.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-018.JPG	**Photo 43-018**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view .** Left side of West elevation.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-019.JPG	**Photo 43-019**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view .** West elevation.

Building #43 - Church

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: 43-101.JPG	**Photo 43-101**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view .** Room 101. East elevation.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-102.JPG	**Photo 43-102**	Extant Record Photographic Key Sheet Page Number:




Photo Description	**Interior view .** Room 101. West elevation.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-103.JPG	**Photo 43-103**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view .** Room 102. South elevation.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-104.JPG	**Photo 43-104**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view .** Room 102. North elevation.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-105.JPG	**Photo 43-105**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view .** Room 103. South elevation.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-106.JPG	**Photo 43-106**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view .** Room 103. North elevation.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-107.JPG	**Photo 43-107**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Interior view .** Room 104. South elevation.

Building #43 - Church

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: 43-108.JPG	**Photo 43-108**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Interior view .** Room 104. North elevation.

Collapsed
Building #A

Collapsed Building A

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: A-101.JPG	**Photo A-101**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the South at the wood decking.

Collapsed Building A

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: A-102.JPG	**Photo A-102**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the Southwest corner.

Collapsed Building A

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: A-103.JPG	**Photo A-103**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** from the West.

Collapsed Building A

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: A-104.JPG	**Photo A-104**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view** from the East.

Collapsed Building A

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: A-105.JPG	**Photo A-105**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** at the perimeter remaining joist framing over existing timber beams.

Collapsed
Building #B

Collapsed Building B

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: B-101.JPG	**Photo B-101**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view.** Wood decking around former building location.

Collapsed Building B

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: B-102.JPG	**Photo B-102**	Extant Record Photographic Key Sheet Page Number:



Photo Description	**Exterior view.** View towards the East. Debris piles around former building location.

Collapsed Building B

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: B-103.JPG	**Photo B-103**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view.** Debris piles around former building location.

Collapsed
Building #C

Collapsed Building C

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: C-101.JPG	**Photo C-101**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view** towards the East. Wood flooring / finishes remain.

Collapsed Building C

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: C-102.JPG	**Photo C-102**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** towards the South at the West end of the floor framing. Wood flooring / finishes remain.

Collapsed Building C

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: C-103.JPG	**Photo C-103**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** towards the South at the East end of the floor framing. Wood flooring / finishes remain.

Collapsed Building C

Photographic Record

As-found Location: Elsa, Yukon

Photo ID Number: C-104.JPG	**Photo C-104**	Extant Record Photographic Key Sheet Page Number:




Photo Description **Exterior view** towards the West. Wood flooring / finishes remain.

Collapsed Building C

As-found Location: Elsa, Yukon

Photographic Record

Photo ID Number: C-105.JPG	**Photo C-105**	Extant Record Photographic Key Sheet Page Number:



Photo Description **Exterior view** down at framing assembly.